



BOHS P406
**Supervision and Management of the safe removal and
disposal of Asbestos**
Training Course Syllabus

Course Title

BOHS P406 Supervision and Management of the safe removal and disposal of Asbestos

Description

This module provides the trainee with the practical knowledge and skills to be able to act as supervisory license holder.

Pre-Qualification

No Pre-qualifications required. But pre-course study recommended if new to subject (details will be provided at time of booking).

Duration

4 days - This course includes a 1 hour 15 minute examination and a full practical assessment. Candidates must pass the written examination AND the practical assessment to be awarded the BOHS Proficiency Certificate in this module.

Content of the BOHS Syllabus

- Asbestos types and health effects - 10%
- Legislation - 10%
- Removal of asbestos - 30%
- RPE, PPE and Decontamination procedures - 10%
- Accident and Emergency procedures - 10%
- Practical - 30%

Day 1

- Asbestos forms and uses
- Health effects of asbestos
- Control limits for asbestos
- Health and Safety at Work Act
- Legislation – Asbestos regulations and ACOPs
- Removal of Asbestos – outline

Day 2

- Removal of Asbestos
- Preparation
- Enclosures
- Removal procedures
- 4-stage clearance
- RPE, PPE & Decontamination procedures
- Accident and emergency procedures

Day 3

- Decontamination units
- RPE and PPE
- Enclosures
- Dust suppression

Day 4

- Final summing-up
- Question and answer session
- Practical training and BOHS Assessment
- BOHS P406 examination – 1hr. 15 minute MCQ paper

Courses offered by Nichol Associates Ltd are subject to our Standard Terms and Conditions, which are available either in writing or from our website at <http://www.nicholassociates.co.uk>